






SB-2000 JSOX Wear Plate



W=28-75



W≥100



C3(all)



Unit:mm




Stanard No.	W	L	w	w ₁	ℓ	ℓ ₁			
SB-2000 JSOX	28	75	-	-	45	15			
		100				25			
		150				25			
	38	75				15			
		100				25			
		150				25			
	48	75				15			
		100				25			
		125				25			
	75	150				50	25	100	50
		200						25	
		75						50	
	100	100				50	25	150	25
		125						50	
		150						50	
	125	200				50	37.5	200	50
		250						100	
		300						150	
	150	150				100	25	100	25
		200						150	
		250						200	

● The above mentioned sizes are only for reference, SinoBronze can produce the parts according to the customers drawings.



SB-2000 JTWX Wear Plate

JTWX

W=28-75



W ≥ 100




Reciprocating Motion

W=28

W=38 · 48

W ≥ 75



Unit:mm

Standard No.	W	L	W ₁	W ₂	φ	φ ₁
SB-2000 JTWX	28	75	-	-	45	15
		100			50	
		125			75	
		150			100	
	38	75			45	15
		100			50	
		125			75	
		150			100	
	48	75			45	15
		100			50	
		125			75	
		150			100	
	75	200			100	25
		75			25	
		100			50	
		150			100	
		200			150	
		100			50	
		125			75	
		150			100	
	100	200			50	25
		250			75	
		300			100	
		200			50	
125	125	75	37.5			
	150	75				
	200	100				
	250	150				
150	300	200	25			
	150	100				
	200	150				
	250	200				

● The above mentioned sizes are only for reference, SinoBronze can produce the parts according to the customers drawings.